

Hyundai i40 Dial fitting



The centre of the original speedo face must be cut away leaving the warning light section in tact as shown.



Position the new dial face over the cut away face and replace plastic ring to cover edge.